

Thor Motor Coach, Inc.

PO Box 1486
701 CR 15
ELKHART, IN 46515
www.ThorMotorCoach.com
Telephone : (800) 860-3812

Serial Number: MAX03470028100
VIN: 1F66F5DN9N0A01279
Order #: 0964750-15

Product Year: 2023
Chassis Year: 2022
Product Chassis F22.0-242

Interior: Biscay Bay
Exterior: Raggae II FBP
Cabinetry: Regatta

Item Number:: MA34.7-23 2023 34.7 Miramar Base Price:: 233,850.00

Standard Equipment

Auto Leveling Jacks w/Touch Pad Controls	12V Attic Fan in Kitchen
Front Paint Protection	Kitchen Countertop LED Accent Lighting
Frameless Windows	Tilt-a-View Inclining Bed Mechanism
Pet-Link™ Multi-Purpose Tie-Down	Oxygenics Shower Head
10" Touchscreen Dash Radio w/ Bluetooth Android Apple	Shower Miser Hot Water Recycling System
Steering Wheel Audio and Camera Control	Bedroom 110V Outlet on Inverter for CPAP
Back-up Monitor	40" TV w/Blu-ray Player in Living Area
Heated, Remote Ext Mirrors w/Side Cameras	32" Television in Bedroom
Reclining/Swivel Captain's Chairs	Exterior 40" TV w/Bluetooth® Soundbar & Radio
Tilt & Telescoping Steering Wheel	USB Charging Ports - Bedroom and Living Room
Automatic Headlamps	Onan RV QG 5500 Gas Generator
Power Roller Shade on Windshield	Dual Roof A/C's
Manual Shade on Cockpit Side Windows	100W Solar Charging System
Valve Stem Extenders on Rear Wheels	Tankless Water Heater
Power Drop-Down Hide-Away Overhead Bunk	Heated/Enclosed Holding Tanks
Leatherette Dream Dinette Booth	1800 Watt Inverter
Single Child Safety Tether	Stackable Washer and Dryer Prep
Double Door Refrigerator	Rapid Camp+™ Multiplex Wiring Control System WiFi
2-Burner Gas Range Top w/Single Induction Cooktop	360 Siphon RV Holding Tank Vent Cap
30" OTR Convection Microwave	WiFi Extender + 4G Connection

Optional Equipment

Cabinetry:Regatta	Surcharge	24,750
Exterior:Raggae II FBP	Leatherette Theater Seats w/Footrests	975
	Total Options::	<u>25,725.00</u>

Base Price:	233,850.00
Total Options:	25,725.00
Total Freight:	2,385.00
Total Amount:	<u>261,960.00</u>

**This is provided as an information resource only.
Previous owner(s) may have removed, altered or
changed equipment after the unit was originally delivered.**