Thor Motor Coach, Inc.

PO Box 1486 701 CR 15 ELKHART, IN 46515 www.ThorMotorCoach.com Telephone :: (800) 860-3812

Serial Number: WAR029M0051164

VIN: 1F65F5DN4N0A18843

Order #: 1102319-09

Product Year: 2023

Chassis Year: 2022

Product Chassis F18.0-190

Interior: Venice Stone

Exterior: Seaport HD Max Cabinetry: Cali Collection

Item Number:: WA29M-23.5 2023 29M Windsport

Base Price::

191,850.00

Standard Equipment

Auto Leveling Jacks w/Touch Pad Controls

Steering Stabilizer

Pet-Link ™ Multi-Purpose Tie-Down

10" Touchscreen Dash Radio w/Bluetooth®,

Apple CarPlay®/

Heated, Remote Ext Mirrors w/Side Cameras

Reclining/Swivel Captain's Chairs

Power Drivers Seat

Power Drop-Down Hide-Away Overhead Bunk

Dream Dinette Booth

Wireless Phone Charger w/USB Plug

Single Child Safety Tether Window Privacy Roller Shades

Double Door Refrigerator

3-Burner Gas Cooktop/Oven w/Glass Cover

Microwave Oven

12V Attic Fan in Kitchen

12V Outlet in Bedroom for CPAP Machine

Bedroom 110V Outlet on Inverter for CPAP

39" TV in Living Area

32" Television in Bedroom

Exterior 32" TV w/Bluetooth® Soundbar & Radio Cable TV & CAT6 Video Distribution Ready

USB Charging Ports - Bedroom and Living Room

Outside Kitchen - Including Refrigerator & Sink

4.0 Micro Quiet Onan Generator

Dual Auxiliary Batteries

Exterior LP Connection

100W Solar Charging System w/Power Controller

Tankless Water Heater

Enclosed Holding Tanks w/Heat Pads

Black Tank Flush System

Shower Miser Hot Water Recycling System

Automatic Generator Start

1000 Watt Inverter

360 Siphon RV Holding Tank Vent Cap

Rapid Camp+™ Multiplex Wiring Control System

WIFI Extender + 4G Connection

Optional Equipment

Cabinetry:Cali Collection Exterior: Seaport HD Max 443

Leatherette Theater Seats w/Footrests

1,163

Dual 13.5 High Efficiency A/Cs, 50 AMP

2,925

Power and Energy

Total Options::

4,531.00

Base Price:

191,850.00

Total Options: Total Freight: 4,531.00 2,535.00

Total Amount:

198,916.00

This is provided as an information resource only.

Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.