



301 Roblin Blvd. PO Box 1230
Winkler, Manitoba, Canada R6W 4C4
Phone: 204-325-4361 Fax: 204-325-5241
A Division of Triple E Canada Ltd.

Manufacturer's Suggested Retail Price

Serial Number U242NMW030684

Item	Part / Description / Details	Quantity	Unit Price	Extended Price
001	664-7053-2021 2021 Unity U24MB USA	EA 1.00	148,015.00	148,015.00
002	664-0040-2021 2020 USA Sprinter 3500 Chassis w/ Upgrades	EA 1.00	0.00	0.00
003	664-0070-2021 Exterior Table	EA 1.00	468.00	468.00
004	664-0044-2021 Fan Upgrade - Thermal Controlled Fans with Rain Sensor in Galley & Lav (n/a of U24RL)	EA 1.00	468.00	468.00
005	664-1048-2021 Flex Solar Panel - 400 Watt	EA 1.00	2,951.00	2,951.00
006	664-0172-2021 Glamour Upper Cabinet Door Upgrade -Grigio Shadow Fenix NTM Matte	EA 1.00	670.00	670.00
007	664-6008-2021 Jacks - 4 Point Leveling System	EA 1.00	2,678.00	2,678.00
008	664-1049-2021 Lithium Upgrade - Dual 12V Lithium Coach Batteries	EA 1.00	3,770.00	3,770.00
009	664-5010-2021 Macerator - Termination w/ manual disconnect	EA 1.00	832.00	832.00
010	664-0047-2021 Remote Key Fob Entry - Coach Entrance Door	EA 1.00	371.00	371.00
011	664-0051-2021 Safe	EA 1.00	403.00	403.00
012	664-6005-2021 Satellite - Auto Acq. Winegard Road Trip T4	EA 1.00	1,879.00	1,879.00
013	664-5007-2021 Generator - 3.6KW Onan LP c/w Auto Start and Auto Changeover Switch	EA 1.00	4,420.00	4,420.00
015	664-0042-2021 Alcoa Dura Bright Aluminum Wheels (6)-outer (4) Dura Bright Finished	EA 1.00	2,815.00	2,815.00
016	00-2960 Freight Out	EA 1.00	3,150.00	3,150.00
	VIN: W1X8E33Y1LN104866 Leather: Mountain Exterior: Silver Cabinetry: Sierra Maple Counter: Concrete			
	FOR SALE IN THE USA ONLY			
Total Manufactured Suggested Retail Price				172,890.00
Manufacturer's Suggested Retail Price does not include state/provincial and local taxes, dealer prep and/or options installed by the dealer. Triple E Recreational Vehicles reserves the right to change prices and specifications without notice.				US Dollars
This is provided as an information resource only. Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.				