



TRIPLE E
RECREATIONAL VEHICLES

301 Roblin Blvd. PO Box 1230
Winkler, Manitoba, Canada R6W 4C4
Phone: 204-325-4361 Fax: 204-325-5241

A Division of Triple E Canada Ltd.

Manufacturer's Suggested Retail Price

Serial Number U242NNW031897

om	Part / Description / Details	Price
11	664-7051-2022 2022 Unity U24CB USA	162,185.00
12	664-1040-2021 2021 USA Sprinter 3500 Chassis. INCLUDES: Comfort Pkg, Comfort DS & PS seat, 7" display, Fog lamps, Cruise control	(4,500.00)
	NOT INCLUDED: Lane keeping assist, Nav, Sat radio, Rain sensor, High beam assist, LED lights, Chrome grill pkg, Heated/Power DS & PS seats	
13	664-5007-2022 Generator - 3.6KW Onan LP with Auto Start and Auto Changeover Switch	4,641.00
14	664-1050-2022 Solar Panels - Rigid Low Profile with control Panel - 400 Watt	3,289.00
15	664-0042-2022 Alcoa Dura Bright Aluminum Wheels (6) - Outer 4 Dura Bright Finished	2,951.00
16	664-0070-2022 Exterior Table	520.00
17	664-6008-2022 Jacks - 4 Point Leveling Jacks	2,951.00
18	664-1049-2022 Lithium Battery Upgrade - Dual 100 Amp Hour 12V Lithium Coach Batteries with Internal Heating System	3,965.00
19	664-5010-2022 Macerator - Termination with Manual Disconnect	910.00
10	664-0171-2022 Overhead Cabinet Door Upgrade - Bianco White Fenix NTM Matte	741.00
11	664-0047-2022 Remote Key Fob Entry - Coach Entrance Door	403.00
12	664-5029-2022 Removable Table between Captain's Chairs (U24CB & U24MB & U24FX Only)	403.00
13	664-0051-2022 Safe	442.00
14	664-5005-2022 U-Lounge Dinette (U24CB only)	884.00
16	00-2960 Freight Out	3,600.00
	VIN: W1X8E33Y5MN183220 Leather: Mountain Exterior: Euro Sport Cabinetry: Vancouver Maple Counter: Antarctica	
	FOR SALE IN THE USA ONLY	
	Total Manufactured Suggested Retail Price	183,385.00
	Manufacturer's Suggested Retail Price does not include state/provincial and local taxes, dealer prep and/or options installed by the dealer. Triple E Recreational Vehicles reserves the right to change prices and specifications without notice.	US Dollars
	This is provided as an information resource only. Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.	