

Thor Motor Coach, Inc.

PO Box 1486
701 CR 15
ELKHART, IN 46515
www.ThorMotorCoach.com
Telephone : (800) 860-3812

Serial Number: MAX03460027222
VIN: 1F66F5DN8M0A06231
Order #: 0885942-06

Product Year: 2022
Chassis Year: 2021
Product Chassis F22.0-242

Interior: Quicksilver II
Exterior: Mood Indigo FBP
Cabinetry: Regatta

Item Number:: MA34.6-22

2022 34.6 Miramar

Base Price:: 217,350.00

Standard Equipment

Auto Leveling Jacks w/Touch Pad Controls
Front Paint Protection
Frameless Windows
Pet-Link™ Multi-Purpose Tie-Down
10.1" Touchscreen Dash Radio w/Bluetooth®, Navigation & Siri
Steering Wheel Audio Control
Back-up Monitor
Heated, Remote Ext Mirrors w/Side Cameras
Reclining/Swivel Captain's Chairs
Tilt & Telescoping Steering Wheel

Automatic Headlamps
Power Roller Shade on Windshield
Manual Shade on Cockpit Side Windows
Valve Stem Extenders on Rear Wheels
Power Drop-Down Hide-Away Overhead Bunk
Leatherette Sofa Bed
Leatherette Dream Dinette Booth
Single Child Safety Tether
Double Door Refrigerator
2-Burner Gas Range Top w/Single Induction Cooktop
30" OTR Convection Microwave

12V Attic Fan in Kitchen
Kitchen Countertop LED Accent Lighting
Tilt-a-View Inclining Bed Mechanism
Bunk Beds Convert to Closet
Bedroom 110V Outlet on Inverter for CPAP

32" Television in Bedroom
39" Exterior TV with Bluetooth Soundbar
Tablet Holder and USB Charge Port In Bunk Beds
USB Charging Ports - Bedroom and Living Room
Outside Kitchen
2.5cf Refrigerator, sink & 1000w Inverter
Onan RV QG 5500 Gas Generator
Auto Transfer Switch w/Power Protection
Dual Roof A/C's
100W Solar Charging System w/Power Controller
Tankless Water Heater
Heated/Enclosed Holding Tanks
1800 Watt Inverter
Stackable Washer and Dryer Prep
Rapid Camp+™ Multiplex Wiring Control System
360 Siphon RV Holding Tank Vent Cap
WIFI Extender + 4G Connection

Optional Equipment

Exterior: Mood Indigo FBP

10,493

Total Options:: 10,493.00

Total Options:: 10,493.00
Base Price: 217,350.00
Total Amount:: 227,843.00

**This is provided as an information resource only.
Previous owner(s) may have removed, altered or
changed equipment after the unit was originally delivered.**