



Thor Motor Coach, Inc.

PO Box 1486
ELKHART, IN 46515
www.ThorMotorCoach.com
Telephone....: (800) 8603812

Serial Number: OMTSV340004963	Product Year: 2023	Interior: Mariposa
VIN: 1FDF6LT1NDA13711	Chassis Year: 2022	Exterior: Lake Powell FBP
Order #: 0945729-23	Product Chassis: F600 4X-fg	Cabinetry: Regatta
Item Number: OMSV34-23	Name: 2023 SV34 Omni	Base Price: \$290,850

Standard Equipment

Auto Leveling Jacks w/Touch Pad Controls	Shower with Glass Door
Ford XLT Pkg w/Center Arms & Headrests	Bedroom 110V Outlet on Inverter for CPAP
Audible Lane Departure Warning	40" TV on Manual Swivel in Cabover
Pre-Collision Assist with AEB and Forward Collision Warning	32" Television in Bedroom
Automatic Headlamps	Exterior 32" LED TV w/Bluetooth Soundbar & Radio
FordPass™ Connect 4G Wi-Fi Modem	Outside Kitchen - Including Refrigerator & Sink
Fog Lamps	USB Charging Ports - Bedroom and Living Room
Rear View Mirror w/Backup Monitor	Winegard® Connect™ WiFi Extender + 4G
Heated Remote Exterior Mirrors	6.0 Onan Diesel Generator
Side View Camera System	Rapid Camp+™ Multiplex Wiring Control System
Keyless Entry for Cab Doors	Auto Transfer Switch w/Power Protection
Valve Stem Extenders on Rear Wheels	Dual Roof A/C's
Aluminum Wheels	Dual Auxiliary Batteries
Leatherette Theater Seats w/Footrests	100W Solar Charging System w/Power Controller
Leatherette Dream Dinette Booth	Whole Coach Water Filtration System
Wireless Phone Charger w/USB Plug	Tankless Water Heater
Single Child Safety Tether	Outside Shower
Double Door Refrigerator	Enclosed Holding Tanks w/Heat Pads
2-Burner Gas Range Top w/Single Induction Cooktop	Shower Miser Hot Water Recycling System
30" OTR Convection Microwave	1800 Watt Inverter
12V Attic Fan in Kitchen	SYNC 3 voice recognition & entertainment system
Kitchen Countertop LED Accent Lighting	

Optional Equipment

Cabinetry:Regatta

Total Options:	_____
Base Price:	\$290,850
Total Options:	
Total Surcharge:	
Total Freight:	\$2,535
Total Amount:	\$290,850

This is provided as an information resource only. Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.