Thor Motor Coach, Inc.

PO Box 1486 701 CR 15 ELKHART, IN 46515 www.ThorMotorCoach.com Telephone .: (800) 860-3812

Serial Number: WAR029M0047857

VIN: 1F65F5DN4M0A06562

Order #: 0826169-14

Product Year: 2022

Chassis Year: 2021 Product Chassis F18.0-190 Interior: Cloud Nine

Exterior: Bay Blue HD-Max Cabinetry: Carolina Cherry

Item Number:: WA29M-22 2022 29M Windsport

Base Price::

166,350.00

Standard Equipment

Auto Leveling Jacks w/Touch Pad Controls
Pet-Link ™ Multi-Purpose Tie-Down

10" Touchscreen Dash Radio w/Bluetooth, SiriusXM Ready

Steering Wheel Audio Control

Heated, Remote Ext Mirrors w/Side Cameras

Tilt & Telescoping Steering Wheel

Automatic Headlamps

Reclining/Swivel Captain's Chairs

Power Drop-Down Hide-Away Overhead Bunk

Stainless Steel Wheel Liners

Leatherette Sofa Bed

Dream Dinette Booth

Window Privacy Roller Shades Double Door Refrigerator

Automatic Generator Start

3-Burner Gas Cooktop/Oven w/Glass Cover

Microwave Oven

12V Attic Fan in Kitchen

Kitchen Countertop LED Accent Lighting

12V Outlet in Bedroom for CPAP Machine Bedroom 110V Outlet on Inverter for CPAP

39" TV in Living Area

32" Television in Bedroom

Exterior 32" LED TV w/Bluetooth Soundbar & Radio

Blu-ray Player in Living Area

HDMI Video Distribution

USB Charging Ports - Bedroom and Living Room Outside Kitchen - Including Refrigerator & Sink

Dual Auxiliary Batteries Exterior LP Connection

Solar Prep (Includes Solar Controller)

6 Gal. Gas/Electric Water Heater

Enclosed Holding Tanks w/Heat Pads

Black Tank Flush System

1000 Watt Inverter

360 Siphon RV Holding Tank Vent Cap

Rapid Camp+™ Multiplex Wiring Control System

WIFI Extender + 4G Connection

Optional Equipment

Cabinetry:Carolina Cherry Exterior: Bay Blue HD-Max Single Child Safety Tether Dual A/C's (w/5.5 Generator and 50-AMP)

2,393

100W Solar Charging System w/Power Controller

278

128

Total Options::

2,799.00

Total Options::

2,799.00

Base Price:

166,350.00

Total Amount::

169,149.00

This is provided as an information resource only.

Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.