

Thor Motor Coach, Inc.

PO Box 1486
701 CR 15
ELKHART, IN 46515
www.ThorMotorCoach.com
Telephone : (800) 860-3812

Serial Number: WAR029M0046495
VIN: 1F65F5DN4L0A11002
Order #: 0828877-10

Product Year: 2021
Chassis Year: 2020
Product Chassis F18.0-190

Interior: Pewter Frost
Exterior: Seville II PP
Cabinetry: Irish Maple

Item Number:: WA29M-21.5

2021 29M Windsport

Base Price:: 148,650.00

Standard Equipment

Auto Leveling Jacks w/Touch Pad Controls
Pet-Link™ Multi-Purpose Tie-Down
10" Touchscreen Dash Radio w/ Bluetooth Android Apple
Steering Wheel Audio Control

Heated, Remote Ext Mirrors w/Side Cameras
Back-up Monitor
Tilt & Telescoping Steering Wheel
Automatic Headlamps
Reclining/Swivel Captain's Chairs
Power Drop-Down Hide-Away Overhead Bunk
Power Drivers Seat
Stainless Steel Wheel Liners
Dream Dinette Booth
Double Door Refrigerator
3-Burner Gas Cooktop/Oven w/Glass Cover
Microwave Oven
12V Attic Fan in Kitchen
Kitchen Countertop LED Accent Lighting
12V Outlet in Bedroom for CPAP Machine

Bedroom 110V Outlet on Inverter for CPAP
39" TV in Living Area
32" Television in Bedroom
Exterior Entertainment Center w/32" TV, Sound Bar & Radio
Blu-ray Player in Living Area
HDMI Video Distribution
Outside Kitchen - 2.6cf Refrigerator & sink
USB Charging Ports - Bedroom and Living Room
Dual Auxiliary Batteries
Exterior LP Connection
Solar Prep (Includes Solar Controller)
6 Gal. Gas/Electric Water Heater
Enclosed Holding Tanks w/Heat Pads
Black Tank Flush System
1000 Watt Inverter
360 Siphon RV Holding Tank Vent Cap
Rapid Camp+™ Multiplex Wiring Control System
WIFI Extender + 4G Connection

Optional Equipment

Cabinetry:Irish Maple
Exterior: Seville II PP 3,375
Frameless Dual Pane Windows 1,275
Leatherette Theater Seats w/Footrests 443

Single Child Safety Tether 98
Dual 13.5 A/C (w/5.5 Generator and 50-AMP) 2,138
100W Solar Charging System w/Power Controller 278

Total Options:: 7,607.00

Total Options:: 7,607.00

Base Price: 148,650.00

Total Amount:: 156,257.00

**This is provided as an information resource only.
Previous owner(s) may have removed, altered or
changed equipment after the unit was originally delivered.**