



ROADTREK

MOTORHOME YEAR:	2021
CHASSIS YEAR:	2021

ZION SRT

CHASSIS SPECIFICATIONS

GPS Navigation -5" Touchscreen Display, Steering Wheel Audio Controls, Voice Command, Media Hub, Stability Control, Rear Park Assist Camera, HD Suspension, 16" Aluminum Wheels, Tire Sealant & Air Compressor, Locking Glove Box, Leather Wrap Telescopic Steering Wheel, Swivel Front Seats, Sirius Sat radio (1 yr sub), Power Folding Mirrors, Fog Lamps, Chrome Grille, Trailer Towing pkg(7/4 pin wiring),PDL, PS/PW/Cruise, Ram Premium Cab Mat.

STANDARD MOTORHOME EQUIPMENT

Custom Painted Coach Skirting & Component Covers , 400 Amp Lithium Battery System, 3,000 watt Sine Wave Inverter, Underhood Generator, 300 watt Solar, Firefly Coach Connect, Fantastic Fan with Remote, 3 Power Entry Steps, Pet Friendly Premium Bug Screen Package, Night Privacy Shades for Cab, 12' Power Awning, Outdoor Shower, 16,000 BTU Auto Propane Furnace, 11,000 BTU Roof Mount Air Conditioning, 25L/30lb LP tank, 5 cu Refer 12V-110V Compressor Operation, 2 Burner LP Stove with Cover, Tankless Insta Hot Water Heater, LP Exterior Quick Connect, 700 watt Microwave, 24" Smart TV with Digital Antenna, 12 Volt Macerator and Gravity Dump Sewage System, Roll Out Pantry and Convenient Pot and Pan Storage, Foldable Counter Top Extension. Forward Facing Rear Folding Power Sofa, creates (74" x 62") Queen Bed.



PO #: VIN: 3C6MRVHG0ME559722

MSRP

REVISION DATE April 23, 2021

CONFIDENTIAL US - DEALER PRICING

ZION SRT Built on RAM Promaster 3500 Regular Length Van w/3.6L V6 6spd Auto	RPZD	136,920.00
---	------	------------

MOTORHOME OPTIONS		
EXTERIOR		
Silver Metallic	SIL	N/C

INTERIOR		
Sterling Pearl Interior - with Ebony Cabinetry, White Granite Countertop, and Platinum Leatherette Seating	STPE	N/C

UPGRADED ACCESSORIES		
Induction Stove	IS	343.00
Sumo Rear Spring System	RS	350.00

OTHER		
Fridge: Vitrifrigo	VIT	350.00
Surcharge: TRANSPORTER FUEL SURCHARGE		350.00

Delivery \$3,400.00
Order Total Cost \$141,713.00

This is provided as an information resource only. Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.