## **Grech Motors**

6915 Arlington Ave. Riverside, CA. 92504 -- 855-99 GRECH

Description	de transcription de la company	0
4 Grech Motors LUSSO Sprinter		\$299,900.0
	Independent Control of	
Interior Features  GRECH Exclusive Seating with Aircraft Style Tray Tables Power recline (Ilmited), power leg lift, heated, cooling and massaging. Power Side Sofas Power Recline into Sleeping Area iPad Control System Bathroom with porcelain toilet and macerator Refrigerator Safe Nespresso machine Microwave Lithionics Batteries - 640Amp Hours Lithium-ion batteries they can run AC for up to six hours Dual Rear A/C Systems Engine Driven A/C 110V Lithium-ion battery powered A/C Front Cab Mat Back-Up Camera Emergency Egress Window Behind Driver LED Accent Lighting Custom Side Wal Covering and Treatments Complete Insulation Package Entry Grab Handle 110/USB Every Row with Inverter  Grech RV Chassis Features* Air Suspension Aluminum Wheels (Black) Turn Signal Camera Custom Fiberglass Ground Effects Custom Stainless Steel Body Molding	Mercedes-Benz Chassis Features*:  4 Cylinder Diesel High Output 208 Horsepower- 332 lb-ft Torque 9G-TRONIC - 9-Speed transmission MBUX Multimedia System with 10.25" touchscreen Mercedes me connect - Wi-Fi (requires subscription) Smartphone Integration Sirius XM Satellite Radio Active Distance Assist DISTRONIC Multifunction Leather Steering Wheel Active Lane-Keeping Asset Active Brake Assist Blind Spot Assist Mirror Attention Assist Wet Wiper System LED High Performance Headlamps Power Driver and Co-drivers seat Heated Driver and Co-drivers seat	
Salesperson posits are non-refundable. Price does not include: Sales Tax, License or Registration. B Riverside, CA	SubTotal Doc Fee Freight Misc. Sales Tax © 0.00% Sales Tax CA DMV Invoice Ref# Balance Due Deposit Rebate Trade-in	\$299,900.  FOB Riverside ( \$0.  \$0.  \$0.4  \$299,900.   \$0.6  \$0.6  \$0.6  \$0.6  \$0.6  \$0.6  \$0.6  \$0.6  \$0.6  \$0.6  \$0.6  \$0.6

This is provided as an information resource only.

Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.