## Thor Motor Coach, Inc.

PO Box 1486 701 CR 15 ELKHART, IN 46515 www.ThorMotorCoach.com Telephone :: (800) 860-3812

Serial Number: OMTXG320004887

VIN: 1FDUF5HT9NEE52546

Order #: 0951957-22

Product Year: 2023

Chassis Year: 2022

Product Chassis F550 4X-fg

Interior: Black Diamond II

Exterior: Lake Powell FBP Cabinetry: Regatta

Item Number:: OMXG32-23

2023 XG32 Omni

Base Price::

285,750.00

## Standard Equipment

Auto Leveling Jacks w/Touch Pad Controls Ford XLT Pkg w/Center Arms & Headrests

**Audible Lane Departure Warning** 

Pre-Collision Assist with AEB and Forward Collision

Warning

Automatic Headlamps

FordPass™ Connect 4G Wi-Fi Modem

Fog Lamps

Rear View Mirror w/Backup Monitor Heated Remote Exterior Mirrors Side View Camera System Keyless Entry for Cab Doors

Valve Stem Extenders on Rear Wheels

Aluminum Wheels

Leatherette Theater Seats w/Footrests Leatherette Dream Dinette Booth Wireless Phone Charger w/USB Plug

Single Child Safety Tether Double Door Refrigerator

2-Burner Gas Range Top w/Single Induction Cooktop

30" OTR Convection Microwave

12V Attic Fan in Kitchen

Kitchen Countertop LED Accent Lighting

Shower with Glass Door

Bedroom 110V Outlet on Inverter for CPAP

40" TV in Living Area

32" Television in Bedroom

Exterior 32" LED TV w/Bluetooth Soundbar & Radio USB Charging Ports - Bedroom and Living Room Winegard® ConnecT™ WiFi Extender + 4G

6.0 Onan Diesel Generator

Rapid Camp+™ Multiplex Wiring Control System

Auto Transfer Switch w/Power Protection

Dual Roof A/C's

**Dual Auxiliary Batteries** 

100W Solar Charging System w/Power Controller

Whole Coach Water Filtration System

Tankless Water Heater

Outside Shower

Heated/Enclosed Holding Tanks

Shower Miser Hot Water Recycling System

1800 Watt Inverter

SYNC 3 voice recongnition & entertainment system

## **Optional Equipment**

Cabinetry:Regatta

Total Options::

0.00

Base Price:

285,750.00

Total Options: Total Freight:

0.00 2,535.00

**Total Amount:** 

288,285.00

This is provided as an information resource only.

Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.