



301 Roblin Blvd. PO Box 1230
 Winkler, Manitoba, Canada R6W 4C4
 Phone: 204-325-4361 Fax: 204-325-5241
 A Division of Triple E Canada Ltd.

Manufacturer's Suggested Retail Price

Serial Number U242NMW030904

Phone (858) 874-8000 Fax () -

Item	Part / Description / Details	Quantity	Unit Price	Extended Price
001	664-7053-2021 2021 Unity U24MB USA	EA 1.00	151,265.00	151,265.00
002	664-0040-2021 2020 USA Sprinter 3500 Chassis w/ Upgrades	EA 1.00	0.00	0.00
004	664-5026-2021 Exterior Ladder -2 piece	EA 1.00	338.00	338.00
005	664-0070-2021 Exterior Table	EA 1.00	468.00	468.00
006	664-0044-2021 Fan Upgrade - Thermal Controlled Fans with Rain Sensor in Galley & Lav (n/a of U24RL)	EA 1.00	468.00	468.00
007	664-1048-2021 Flex Solar Panel - 400 Watt	EA 1.00	2,951.00	2,951.00
008	664-6008-2021 Jacks - 4 Point Leveling System	EA 1.00	2,678.00	2,678.00
009	664-0049-2021 Leisure Lounge Plus (U24MB Only)	EA 1.00	2,678.00	2,678.00
010	664-5010-2021 Macerator - Termination w/ manual disconnect	EA 1.00	832.00	832.00
011	664-0047-2021 Remote Key Fob Entry - Coach Entrance Door	EA 1.00	371.00	371.00
012	664-5029-2021 Removable Table b/w Captain's Chair (U24CB & U24MB & U24FX Only)	EA 1.00	371.00	371.00
013	664-0051-2021 Safe	EA 1.00	403.00	403.00
014	664-6005-2021 Satellite - Auto Acq. Winegard Road Trip T4	EA 1.00	1,879.00	1,879.00
015	664-5007-2021 Generator - 3.6KW Onan LP c/w Auto Start and Auto Changeover Switch	EA 1.00	4,420.00	4,420.00
017	664-1049-2021 Lithium Upgrade - Dual 12V Lithium Coach Batteries	EA 1.00	3,770.00	3,770.00
018	00-2960 Freight Out	EA 1.00	3,350.00	3,350.00
	VIN: W1X8E33Y8LN121499 Leather: Earth Exterior: White Suede Cabinetry: Sierra Maple Counter: Concrete			
	FOR SALE IN THE USA ONLY			
Total Manufactured Suggested Retail Price				176,242.00
<p>Manufacturer's Suggested Retail Price does not include state/provincial and local taxes, dealer prep and/or options installed by the dealer. Triple E Recreational Vehicles reserves the right to change prices and specifications without notice.</p> <p>This is provided as an information resource only. Previous owner(s) may have removed, altered or changed equipment after the unit was originally delivered.</p>				US Dollars