

Thor Motor Coach, Inc.

PO Box 1486
701 CR 15
ELKHART, IN 46515
www.ThorMotorCoach.com
Telephone : (800) 860-3812

Serial Number: MAX03470028108
VIN: 1F66F5DN8N0A01273
Order #: 0964746-17

Product Year: 2023
Chassis Year: 2022
Product Chassis F22.0-242

Interior: Moonstone
Exterior: Steel Band FBP
Cabinetry: Shell Gray

Item Number:: MA34.7-23

2023 34.7 Miramar

Base Price::

233,850.00

Standard Equipment

Auto Leveling Jacks w/Touch Pad Controls
Front Paint Protection
Frameless Windows
Pet-Link™ Multi-Purpose Tie-Down
10" Touchscreen Dash Radio w/ Bluetooth Android Apple
Steering Wheel Audio and Camera Control
Back-up Monitor
Heated, Remote Ext Mirrors w/Side Cameras
Reclining/Swivel Captain's Chairs
Tilt & Telescoping Steering Wheel
Automatic Headlamps
Power Roller Shade on Windshield
Manual Shade on Cockpit Side Windows
Valve Stem Extenders on Rear Wheels
Power Drop-Down Hide-Away Overhead Bunk
Leatherette Dream Dinette Booth
Single Child Safety Tether
Double Door Refrigerator
2-Burner Gas Range Top w/Single Induction Cooktop
30" OTR Convection Microwave

12V Attic Fan in Kitchen
Kitchen Countertop LED Accent Lighting
Tilt-a-View Inclining Bed Mechanism
Oxygenics Shower Head
Shower Miser Hot Water Recycling System
Bedroom 110V Outlet on Inverter for CPAP
40" TV w/Blu-ray Player in Living Area
32" Television in Bedroom
Exterior 40" TV w/Bluetooth® Soundbar & Radio
USB Charging Ports - Bedroom and Living Room
Onan RV QG 5500 Gas Generator
Dual Roof A/C's
100W Solar Charging System
Tankless Water Heater
Heated/Enclosed Holding Tanks
1800 Watt Inverter
Stackable Washer and Dryer Prep
Rapid Camp+™ Multiplex Wiring Control System WIFI
360 Siphon RV Holding Tank Vent Cap
WIFI Extender + 4G Connection

Optional Equipment

Cabinetry:Shell Gray
Exterior:Steel Band FBP

1,425

Surcharge
Leatherette Theater Seats w/Footrests

24,750

975

Total Options:: 27,150.00

Base Price: 233,850.00
Total Options: 27,150.00
Total Freight: 2,385.00
Total Amount: 263,385.00

**This is provided as an information resource only.
Previous owner(s) may have removed, altered or
changed equipment after the unit was originally delivered.**