

# Thor Motor Coach, Inc.

PO Box 1486  
701 CR 15  
ELKHART, IN 46515  
www.ThorMotorCoach.com  
Telephone : (800) 860-3812

<b>Serial Number:</b> GCE24TT0018630	<b>Product Year:</b> 2023	<b>Interior:</b> Grey Cashmere
<b>VIN:</b> W1X8E33Y3NN197408	<b>Chassis Year:</b> 2022	<b>Exterior:</b> Blue Ridge FBP
<b>Order # :</b> 0976207-19	<b>Product Chassis</b> SP11+	<b>Cabinetry:</b> Miami Modern

---

<b>Item Number::</b> GC24TT-23	<b>2023 24TT Delano</b>	<b>Base Price::</b>	<b>196,650.00</b>
--------------------------------	-------------------------	---------------------	-------------------

---

## Standard Equipment

Frameless Windows	12V Outlet in Bedroom for CPAP Machine
Mercedes-Benz Multimedia Dash Radio with Bluetooth®	Shower Miser Hot Water Recycling System
Rear View Mirror w/Backup Monitor	32" TV in Living Area
Heated Remote Exterior Mirrors	32" Television in Bedroom
Upgrade Windshield Privacy Close off Panels	Bluetooth Coach Radio System w/DVD Multimedia Receiver
Swivel Driver/Pass Chairs w/2 Filler Cushions	Rapid Camp+™ Multiplex Wiring Control System
Removable Table Between Cockpit Seats	3.6 Onan LP Generator
Cockpit Carpet Mat	Winegard Connect WiFi/4G/TV Antenna
Aluminum Wheels w/Valve Stem Extenders	Single HO Roof A/C
Dash Applique	Auxiliary House Battery
Cabover Sleeping Area w/Bunk Ladder	100W Solar Charging System w/Power Controller
Leatherette Dream Dinette Booth	1000 Watt Inverter
Double Door Refrigerator	Tankless Water Heater
Pop-up Outlet & Charging Station Kitchen Ctop	Outside Shower
2-Burner Cooktop w/Glass Cover & Electric Start	Exterior LP Connection
Convection Microwave	Holding Tanks w/Heat Pads
Electronics Power Charging Station	Black Tank Flush System

---

## Optional Equipment

Exterior:Blue Ridge FBP	Single Child Safety Tether	98
Auto Leveling Jacks w/Touch Pad Controls	4,493	
<b>Total Options::</b>		<b>4,591.00</b>

---

Base Price:	196,650.00
Total Options:	4,591.00
Total Freight:	2,535.00
<b>Total Amount:</b>	<b>203,776.00</b>

---

**This is provided as an information resource only.  
Previous owner(s) may have removed, altered or  
changed equipment after the unit was originally delivered.**